



A publication of Tucker Sno-Cat® Corporation
NO SNOW TOO DEEP

Made in the USA since 1942
NO ROAD TOO STEEP

October 2009 Volume 1 Issue 2

The Cat's Meow..

Tucker Sno-Cat® Corp. would like to give our customers a tip for the month. With winter coming fast I'm sure you are getting your machines serviced and ready for the upcoming season. After you get your machine serviced be sure and operate all functions to insure that nothing will go wrong on that first trip out. Also do not forget about the trailer! You should load the machine on the trailer and check things like tie-down straps, tires, brakes, lug nuts, lights etc.. Regardless of how well the machine operates the trailer that gets it to the snow must also be serviced and maintained. Be sure and contact us with any questions or concerns.



FACTORY SERVICE SEMINAR

Our second fall factory service seminar is October 20-21. This seminar will cover new as well as older machines. Please e-mail John Meilicke (john@sno-cat.com) for further information.

SERVICE TIP

LUCAS FIFTH WHEEL & SLIDER BLOCK LUBE

At times you may experience a squeaking noise coming from under your machine while steering. This is usually caused by dry slide blocks on the front and rear fifth wheel plates. We have found that by applying "Lucas Fifth Wheel & Slider Lube" between the slide blocks and fifth wheel plates to be quite effective in eliminating the squeaking from the steering system. You will also notice the machine will steer smoother and easier.

Lucas Fifth Wheel & Slider Lube is available at most truck stops and Napa Auto Parts stores.



VEHICLE OPERATION REMINDERS:

- * DO NOT SPIN THE TRACKS.
- * ONLY STEER VEHICLE WHEN THE MACHINE IS MOVING.

Tucker Sno-Cat® Corporation
2872 S. Pacific Hwy
Medford, OR 97501

www.sno-cat.com
(541) 779-3731
Toll Free (866) 766-2281